

KT07



POWER SUPPLY REPAIR KIT

VESTEL POWER BOARD 17PW16 / 17PW20

A 10 piece power supply repair kit for these vestel power boards.

The symptom is the mains input fuse blowing.

F300	P9NK50ZFP
IC802	FAN7529
Q803	P9NK50ZFP
D824	STT12R06FP
R830	0.22R 3W
IC806	FSDL321
IC801	PC123
IC825	STPS5125B
D851	TL431 SMD
D836	8V2 ZENER SMD

We recommend all kits are fitted by qualified engineers

We accept no responsibility for loss, injury or damage caused by your use of this kit as a successful repair depends on your own skill and fault finding ability.