

POCKET SCALE

Ref. No. 456.057

For the purpose of using and maintaining the kitchen scale, please read this instruction completely before operating.

Specifications

| | |
|----------------------------|-------------------------|
| Capacity | 0.1g-500g |
| Show numerical value | 0.1g |
| Battery | 2pcs AAA batteries (3V) |
| Work temperature | 5° - 60°C |
| Display usage | LCD Show, 4 units |

Features:

- Equipped with a high precision sensor and high capability CPU to ensure weighing accuracy.
- Capacity: 0.1g-500g
- Tare function.
- Auto power off
- Low voltage indication

KEY FUNCTIONS

ON/OFF key: Power on, Power off.

TARE key: Tare function.

UNIT key: To select the measuring units for g/kg/lb/oz.

LIGHT key: Backlight illumination.



OPERATION

Take out the scale, and open up the battery cover, install the batteries in the battery compartment. Put the scale on a flat table, and ensure it steady.

WEIGHING STEPS

Under the state press the key "ON/OFF" to power on, the scale will be zero "0.00" appear on the display after 2 seconds.

Press the UNIT key, you can change "g", "kg", "lb", "oz".

Under the weight state, put the container on the glass, LCD will show the weight of container.

Press the key "TARE", LCD shows "0". Clear the weight of the container, then put the food into container, the weight will appear on the display.

Press the key "ON/OFF" again , power off.

In bad lighting conditions press the LIGHT key to illuminate display, press again to turn off.

ERROR DISPLAY

When the scale is over loaded, the "EEEE" will appear on the display.

When the screen shows "E", it means that the power isn't enough, please change the batteries as soon as possible.

When the screen shows "OUTZ" or "UNST", and power off. It means the object over loaded or unsteady.

INSTALLING THE BATTERIES

Use 2pcs AAA batteries. When changing the battery, please open the battery cover on the back and put AAA batteries into the battery compartment (observe correct polarity), then close the battery cover tight.

ADVICE FOR USE AND CARE

Put the scale on a clean and flat table.

The max. weight of the scale is 500g, which included the weight before tare.

To ensure the life of the scale, do not put the scale under wet, hot & cold condition.

The product belongs to high precision electronic weighing apparatus, please do not press or drop the scale otherwise the scale is easy to damage.

If the scale surface is dirty, please clean the scale with soft cloth, do not use any chemical detergent and allow water to get inside the scale.