

MODKIT 50

PHOENIX KITS



Philips LO1.1E Chassis

Models 28PT4457/05, 28PW5407/05, 28PW6006/05

“Set Dead” The following components should be replaced.

Qty	P/Number	Type	Cct Ref
1	BC847B = BC846B	Transistor	7522
1	ON3171 = TCET1103	Opto Coupler	7515
1	1N4148	Diode	6523
1	TEA1507P	I.C	7520
1	STP10NK80ZP	Transistor	7521
1	47 Ohm	Safety Resistor	3523

Our MODKIT56 contains a full range of components to repair this chassis

Since the end result depends on your own skill and fault finding ability, the supplier will accept no responsibility for loss, damage or injury caused by your use of this kit. This is expressly sold on the above understanding and that the decision to use the kit is the responsibility of the kit user.

See an up to date listing of all our kits on our Web site :-
phoenixkits.co.uk

October 2005