

MODKIT 64

PHOENIX KITS



PANASONIC DMRE55

To repair fault :-
Int shutting down
with "System Check" Displayed.

Fitting the following components
should cure the fault.

Kit Contains

1	STRG6353	IC001
1	MA2J72800L	D007 (White)
1	MA4068N	ZD002
1	MA8051	ZD004
1	RD6.2ESB	ZD107

Since the end result depends on your own skill and fault finding ability, the supplier will accept no responsibility for loss, damage or injury caused by your use of this kit. This is expressly sold on the above understanding and that the decision to use the kit is the responsibility of the kit user.

See an up to date listing of all our kits on our Web site :-

phoenixkits.co.uk

February 08