

KT02



POWER SUPPLY REPAIR KIT

BUSH MAXIM 1157 1154 Medion
Goodmans (Standard) 04TA069I 05TA71B 05TA071C

A standard power supply repair kit for faults attributed to the standby +5v rail.

BUSH IDLCD27TV006.
MAXIM 1154, 1157.
MEDION MD30112.
GOODMANS IDLCD27TV006.

The numbers off the boards will read: 04TA069I 26" 27" 30" 32"
& 05TA71B, 05TA071C.
LCD TV POWER SUPPLY PROFILO-TELRA.

**Please check the primary of TR20 before fitting the kit.
Primary windings should read approx 2.700mH / 4.00 Ohm.**

F300	T3.15A FUSE
IC21	FSD200
IC30	ICE1QS01
D315	12V ZENER
D318	2V4 ZENER
Q300	BC337
Q302	BC848C SMD
D325	1N4007
C213	33UF
C322	47UF
C356	47UF
LINK	(IF NEEDED)

We recommend all kits are fitted by qualified engineers

We accept no responsibility for loss, injury or damage caused by your use of this kit as a successful repair depends on your own skill and fault finding ability.